



WEEKLY CONSTRUCTION REPORT
FOR November 18, 2019

1. Benson Avenue Exterior Water Tank Painting

- Atlantic City Electric work is complete
- Scaffolding installation is complete
- The contractor is preparing to install the containment system
- During construction, access on Benson Avenue will be limited

2. Reconstruction of Atlantic Ave – Fredericksburg Ave to Clermont Ave

- Concrete work is complete on the bay side of Atlantic Avenue
- Underground utility work is almost complete on the ocean side of Atlantic Avenue
- Concrete work is in progress on the ocean side of Atlantic Avenue

3. Safe Routes to Schools Project – Various Locations

- Drainage, concrete work, and paving is complete at all locations
- Striping and signage is nearing completion